

Pulsarlube Solution at PA Paper Mill

Date Installed – 12/6/2007

Problem

Pumps located in an obscure area of plant, subjected to outside Temperatures but pumps are under cover. Pumps suppose to get greases regularly but it does not happen. They run 24/7 and have had some failures do to dry running.

Solution Installed a Pulsarlube M with a six point divider block and hooked up to 3 pumps. To date there have been no problems.



